




FIG4

F166










		G	Н	
1	Events	ON	OFF	
Z	Gob Interceptor	334	1	4
3	Blanks Close	324	13	0
4	Blanks Open	130	32	1
5	Plunger Up	33	12	:3
5	First Baffle	9	12	25
7	Plunger Down	127	32	27
8	Funnel	1	15	50
9	Settle Blow	1		1
10	Plunger Cooling	150	2	60
11	Invert	200	2	60
12	Neckring Open	274.	5 2	83
13	Revert	28	2 1	72
14	Molds Close/Open	22		70
15	Mold Cooling	1		50
16	Blowhead	29	0 1	13
17	Final Blow	34	8	120
18	Take Out IN	13	37	197
19	Tongs Close	17	78	78
20	Take Out OUT	19	97	90


Fig- 11



FIG







· MOTION OURATIONS

F19-14

